



Albany Grain Silo Repairs

PROJECT DETAILS

Centrals have been contracted to perform extensive concrete repairs to the 10,000T grain storage silos located at CBH's Albany Port Facility.

The scope of works includes hydro-demolition, reinforcing steel repair/preparation, guncrete reinstatement and the application of protective coatings to more than 10,000m² of surface across the walls of the ten concrete silos.

Particular attention has been applied to the safety work systems on site as the 35m high structures pose a potential working at heights hazard. To protect the environment, Centrals have deployed a full containment system to manage all demolition waste including run-off water from the hydro-demolition.


Client: Cooperative Bulk Handling (CBH)

Location: Albany, WA

Duration: 20 months

Completion: Ongoing

Value: \$7.5m



PROJECT HIGHLIGHTS

Personnel on Site: 20

Manhours: 36,211

Products: 1,000m² Parchem Guncrete,
24,000m² Parchem Emerstop Silane